

s1221 - F11 / P1661 / ECU - L1/L2 pulses comparison fault 2
s1221 - F11 / P1662 / ECU - injection lock fail after a power latch
s1221 - F11 / P1663 / ECU - reset fail after a power latch
s1221 - F11 / P1690 / ECU - QADC slope high fault
s1221 - F11 / P1691 / ECU - QADC slope low fault
s1221 - F11 / P1692 / ECU - QST timeout fault
s1221 - F11 / P16D2 / ECU - Reduced torque mode fault
s1221 - F11 / P16D6 / ECU - engine speed fault
s1221 - F11 / P16D8 / ECU - Pedal monitoring fault
s1221 - F31 / P1978 / ECU - ESC timeout fault
s1485 - F7, F11 / P0685 / Main relay fault
s1612 - F3, F6, F11 / P062D / Injector Bank 1 fault
s1613 - F3, F6, F11 / P062E / Injector Bank 2 fault
s3253 - F11 / P1452 / DP sensor tubes inverted
s3253 - F11 / P1453 / DP sensor tube Clamped
s3253 - F7 / P244A / DP sensor leak detected
s3253 - F2 / P2453 / DP sensor plausibility fault
s3253 - F4 / P2454 / DP sensor low fault
s3253 - F3 / P2455 / DP sensor high fault
s5202 - F31 / U0140 / CAN message Time-out fault

2700EL HES
27003121 Q
RH 10008700
Roper