



**REVERSE**



**AUGER  
BIT**



**FORWARD**

9700039

**UP**



**AUGER  
CYLINDER**



**DOWN**

**WARNING**

**HIGH PRESSURE FLUID HAZARD**  
 Injury or death  
 occurs before repairing.

- Do not operate with any safety shield or guard removed or modified. Keep in good working order.
- Before operating or moving the machine, clear work area of all children and untrained personnel.
- Keep hands, legs, feet, hair, jewelry and clothing away from all moving parts.
- Always use the post hinged hold post. Never hold post with any part of your body.
- Fully lower poulcher head before transporting. Use safety chains to transport.
- Keep away from overhead and buried power lines. Arcing and possible electrocution can occur even without direct contact.
- Consult local utility companies before operating machine near overhead or buried power lines or