

A photograph of a white mechanical component, possibly a winch or a similar device, mounted on a concrete surface. The component has a central shaft and two chains attached to it. A red arrow points to a dark, wet area on the shaft, indicating a leak. A text box in the upper right corner contains the text: "It is leaking in this area. Housing area is dry." The housing area is dry, while the area where the shaft meets the housing is wet and dark, suggesting a leak of oil or another fluid.

It is leaking in this area.
Housing area is dry.